

INDIVIDUAL ASSISTANCE STREET SHEET FILLABLE

County	Name of Community	Date			Assessor's Name/Phone Number						
Hamilton	Cincinnati - Westwood Neighborhood	3/22/2017			John Smith (Building Dept.) - 513-555-1234 ext. 316						
Location (Street Address, Apt/Condo, Complex, MH Park)		Type of Structure	Status	Depth of Water	Insurance	Local Preliminary Determination				State Use Only	
						D	Maj	Min	A		
1070 Winding Way		SF <input checked="" type="checkbox"/> MH__ Apt__ Condo__ Business__	Own <input checked="" type="checkbox"/> Rent__	Basement __ ft __ in First Floor __ ft __ in Crawl Spc __ ft __ in	Flood__ NONE Homeowners__ Renter__ Sewer B/U Rider__					✓	
Comments:	Tree limb through detached garage roof, car damaged, garage door can't open.										
4222 Oak Creek Pkwy		SF <input checked="" type="checkbox"/> MH__ Apt__ Condo__ Business__	Own <input checked="" type="checkbox"/> Rent__	Basement __ ft __ in First Floor __ ft __ in Crawl Spc __ ft __ in	Flood__ NONE Homeowners__ Renter__ Sewer B/U Rider__			X			
Comments:	Dozens of shingles missing on one side of home, damage to chimney.										
620 Deerpath Way, Units 1-6		SF__ MH__ Apt <input checked="" type="checkbox"/> Condo__ Business__	Own__ Rent <input checked="" type="checkbox"/>	Basement __ ft 4 in First Floor __ ft __ in Crawl Spc __ ft __ in	Flood__ Homeowners__ Renter <input checked="" type="checkbox"/> Sewer B/U Rider__				2		
Comments:	Two basement, two first level, two second level apartments. Basements units (Unit 1 and Unit 2) with water damage, upper units unaffected.										
710 West River Road		SF__ MH__ Apt__ Condo <input checked="" type="checkbox"/> Business__	Own__ Rent <input checked="" type="checkbox"/>	Basement 6 ft __ in First Floor __ ft __ in Crawl Spc __ ft __ in	Flood__ Homeowners__ Renter__ Sewer B/U Rider <input checked="" type="checkbox"/>			1			
Comments:	6 feet of water in basement, washer/dryer, furnace and water heater most likely ruined										
100-198 Wellington Road		SF <input checked="" type="checkbox"/> MH__ Apt__ Condo__ Business__	Own__ Rent__	Basement __ ft __ in First Floor __ ft __ in Crawl Spc __ ft __ in	Flood__ Homeowners__ Renter__ Sewer B/U Rider__			4	16		
Comments:	20 homes, 10 on each side of Wellington Road between Tates Creek and River Road. 16 homes had some basement flooding, water levels between 2-4". 192, 194, 196 and 198 all had between 12-16" of water in the basement, mechanics affected. Unknown insurance since most owners were not home, but lower income area. Water levels evaluated from discussions with some owners and neighbors and from curb assessment.										
Rev. 5/2015	Total for page:								6	19	